

1002-11-3 Elect./Hyd.Valve Assembly, Tomato

<u>Ref</u>	<u>Part No.</u>	<u>Description</u>	<u>Parts – Assembly</u>	<u>Will Fit SN</u>	<u>Remarks</u>
0	TL-790-KIT	Brand Valve Repair Kit	0		
1	HVE-1036C	Unloaded Inlet Section	1		
2	HVE-1036BL	Brand Valve Section with Locks	5	HVE-1076, HVE-3046,	Complete, w/o Cartridges & Coils
3	HVE-1046-RL	Valve Section With Relief on Port B	1	HVE-1076	Complete, w/o Cartridges & Coils
4	HVE-1037N	Series 36 Floating Section, Detent, w/no wire	2	HVE-1076	Complete, w/o Cartridges & Coils
5	HVE-1036S	Shim (Between Sections)	24		
6	HVE-1037O	O-Ring, Buna N 90 Durometer	24		
7	HVE-1037M	Tie Rod Kit for Tomato Harvester	1		
8	HVE-1046Z	End Plate, Valve Stack	1		
9	HVE-1046C	Plug, End Section, Brand Valve	3		
10	HVE-1037Q	Backup for O-Ring (Parker #3-012)	3		
11	HVE-1037H	O Ring (Parker #2-012)	3		
103	BL-5-LW	5/16 SPLIT LW ZC	6		
104	BL-5-N	5/16 UNF FIN HEX NUT A563 GrA ZINC	6		

1002-11-3 ELECT/HYD. VALVE ASSEMBLY

NOTE:
TORQUE NUTS
(ON LONG BOLTS)
TO 95 Inch/Lbs.

