

1002-6-7 Cross Conveyor Drive Shield Assembly

<u>Ref</u>	<u>Part No.</u>	<u>Description</u>	<u>Parts – Assembly</u>	<u>Will Fit SN</u>	<u>Remarks</u>
1	BRA-0022	Bracket, Cross Conveyor Drive Shaft Sprocket	1		
2	DC-1176	Decal, Danger-Hand Chain Sprockets	1		
3	MOU-0004	Mount, Shield, Rear Cross Chain Shield	1		
4	SHD-0004	Shield, Motor, Rear Sorting Conveyor	1		
5	SP-5017-T	Idler, 17 tooth x #50 Chain	1		
6	CH-50-53	Roller Chain, 53 pitches, #50 Roller Chain, w/master link	1		
100	BL-4-100-H	1/4-20 X 1 HEX CAP G5 ZC	2		
101	BL-4-FW	1/4 USS FW ZC	4		
102	BL-4-LN	1/4-20 HEX LN NE ZC	2		
103	BL-6-100-H	3/8 UNC X 1 HH C/S BOLT GR5 ZINC	1		
104	BL-6-125-H	3/8-16 X 1 1/4 HHCS G5 ZC	1		
105	BL-6-LN	3/8 UNC FIN HEX LOCK NUT NE A563 GrA ZINC	2		
106	BL-6-SW	3/8 SAE FW ZC	2		
107	BL-8-150-H	1/2 UNC X 1 1/2 HH C/S BOLT GR5 ZINC	1		
108	BL-8-225-C	1/2 UNC X 2 1/4 CARRIAGE BOLT GR5 ZINC	1		
109	BL-8-LN	1/2-13 HEX LOCK NUT NYLON INSERT ZC	1		
110	BL-8-LW	1/2 SPLIT LW ZC	1		
111	BL-8-N	1/2-13 HEX FIN NUTS ZC	1		
112	BL-8-SW	1/2 SAE FW ZC	7		

1002-6-7 CROSS CONVEYOR DRIVE SHIELD ASSEMBLY

