

1105-3-6 Header Dirt Vibrator Assembly

<u>Ref</u>	<u>Part No.</u>	<u>Description</u>	<u>Parts – Assembly</u>	<u>Will Fit SN</u>	<u>Remarks</u>
1	SFT-8301	Vibrator Shaft, Secondary Header, High Cap Tomato	1		
2	BR-085-RAK	Bearing Housing (1 3/4") Main Shaker	2	19101	
3	BR-175-085	Fafnir Bearing 1 3/4 Tri Seal	2		
4	CPJ-6051	Coupler, Motor Side 1in. bore	1	19101	Sub 194-6053
5	CPJ-6055	Coupler, Urethane Spider	1	19101	For use with CPJ-6052 and CPJ-6051 Sub CPS-6053
6	CPJ-6052	Coupler, Shaft side 1 1/4in. bore	1	19101	Sub 194-6053 Except on Debris Fan
7	HM-115	Hydraulic Motor	1		
8	BRA-8106	Bracket, Motor Mount, Dirt Vibrator, HC290	1		
9	RLT-027-108	Roller 2.75" dia. 1/2" Bore	4		2755C1X (Old Number, Single Bearing)
10	GF-1428	Grease Fitting 1/4" x 28 straight	2		
11	192-163	Cleaner bar bracket	1	19101-	

1105-3-6 HEADER DIRT VIBRATOR ASSEMBLY

