

4002-11-7 Elect./Hyd. Valve Section, Float w/Detent

<u>Ref</u>	<u>Part No.</u>	<u>Description</u>	<u>Parts – Assembly</u>	<u>Will Fit SN</u>	<u>Remarks</u>
1	HVE-1036P	Coil	2		Replaces HA-431-B on Manifold Block.
2	HVE-1036M	Work Section Cartridge	2		
3	HVE-1037P	O-Ring	4		
4	HVE-1036T	Detented End Cap (2 inside grooves)Stamped "TB"	1	HVE-1037N	
5	HVE-1036X	"O" Ring for End Cap	2		
6	HVE-1036V	Detent Ball for HVE-1037N	2		
7	HVE-1036U	Detent Spring, HVE-1037N	1		
8	HVE-1046J	Detent Ball Housing for 36BFXD	1		
9	HVE-1046N	Detent End Spacer for Detent Section	1		
10	HVE-1036E	Valve Spool	1		
11	HVE-1046M	End Spacer for Detent Section	1		
12	HVE-1036Y	Spool Spring for End Cap	1		Replaces # HVE-1036L
13	HVE-1036W	End Cap	1		
14	A-6408-8	8 SAE Plug	1		

4002-11-7 ELECT./HYD. VALVE SECTION, FLOAT W/DETENT

